

TO: ALL REGENCY COMMUNICATIONS PROFESSIONAL SALES AND SERVICE CENTERS
ALL REGENCY COMMUNICATIONS PROFESSIONAL SALES REPRESENTATIVES

MODELS AFFECTED: RH250A,B,C,UK; RH256A,B,C,UK VHF TRANSCEIVERS RHTM256A,B,C,UK TRUNK MOUNT VHF TRANSCEIVERS

To eliminate the possibility of regeneration of the Power Amplifier P.C. Board after radio is unkeyed, a 47pF (1524-0470-002) capacitor has been added from the base of Q301 to ground. The reference designator will be C323 and will be added to all radios manufactured after April 1984. If you have a radio with this tendency, C323 may be added on the component side of the P.C. Board as shown in Figure 1. Please make the necessary additions to your Service Manual.

TECHNICAL SERVICE DEPARTMENT REGENCY COMMUNICATIONS, INC.



